

SALVAGE INTIMATION SHEET

Sr. No.	Description	Case Detail
1	Case ID	SM/26-27/Jun/WB/515
2	Description of Material	Turbine and Rotor Parts
3	Location	VILL - KASBERA, PO - SHINRAMNAGAR, HALDIA , PURBA MEDINAPUR, WB. EAST MIDNAPORE
4	State	West Bengal
5	Quantity	As per List
6	Unit	As per List
7	Cause of Loss	Breakdown Generator Rotor Earth fault
8	Reserve Price	Rs. 9,00,000/- (Without Taxes)
9	Minimum Bid Increment	Rs. 1,000/-
10	Date of Physical Inspection	June 17, 2026 - June 19, 2026
11	Time of Physical Inspection	11:00 am - 5:00 pm
12	Date of Auction	June 19, 2026
13	Time of Auction	3:00 pm - 4:00 pm
14	Remarks	File/SM/PQRSI/26



info@saalvagemaasterz.com
reachus@saalvagemaasterz.com
contact@saalvagemaasterz.com

+91-9888006654
+91-9888006653
+91-9888006652

Head Office :
46, Janta Market Building,
Sector - 27 D, Chandigarh - 160019

Corporate & Registered Office : SOHO- 313, Block-B, 3rd Floor, Chandigarh Citi Centre (CCC), VIP Road, Zirakpur - 140603